

## Proposed Code Change State Form 41186R

RETURN TO: INDIANA DEPARTMENT OF HOMELAND SECURITY CODE SERVICES SECTION 302 W. Washington Street Room W246

Indianapolis, IN 46204

INSTRUCTIONS:

Only TYPED copy accepted.

(KEY - Dashed line through material to be deleted, underline material to be added)

FOR OFFICE USE ONLY

Received 6-20-09

Code 62.6.5-09

| Use second sheet for any material requiring more space.  |                |                |
|--|----------------|----------------|
| Code Title   |                | Edition        |
| Indiana Residential Code   |                | 2009           |
| Section number and title   |                | Page           |
| E3905.13.2.2   |                | 697            |
| Proponent Title  |                |                |
| Charlie Eldridge   | Consultant     |                |
| Address  |                | Phone          |
| 551 Grassy Ln., Indianapolis, IN 46217   |                | (317) 370-3444 |
| PROPOSED CODE CHANGE (Check One)   |                |                |
| ☐ Change to read as follows ☐ Add to read as follows ☐ Delete and substitute as follows ☐ Delete without substitution  |                |                |
| E3905.13.2.2 Clamp fill. Where one or more internal cable clamps, whether factory or field supplied, are present in the box, a single volume allowance in accordance with Table E3905.13.2.1 shall be made based on the largest conductor present in the box. No allowance shall be required for a cable connector with its clamping mechanism outside the box or for clamps that are an integral part of a nonmetallic box that does not protrude more than 1/8 in. into the box. |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
| REASON AND FISCAL IMPACT   |                |                |
| Many nonmetallic boxes have a flapper style of clamp for Type NM cable that should not be counted when calculating box fill. I see this as a non-issue for a single home; however, this could be an issue with a volume builder.   |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
|  |                |                |
| DEVIEW DE CO.  | # 45 ND 4 TION |                |
| REVIEW RECOMMENDATION  |                |                |
| Approve  |                |                |
| Disapprove   |                |                |
| Approve as amended   |                |                |
| Further Study  |                |                |